Oil Field Environmental Incident Summary

Responsible Party: Enerplus Resources

Well Operator: ENERPLUS RESOURCES USA CORPORATION

Well Name: NET 149-92-30B-31H

Field Name: HEART BUTTE Well File #: 22240

Date Incident:1/20/2014Time Incident:02:00Facility ID Number:County:DUNNTwp:149Rng:92Sec:19Qtr:

Location Description: While producing, the polished rod broke causing oil to mist out of the well. The

released volume is estimated to be 64 gallons. Oil was released onto the well pad, approximate 45 mile per hour winds carried some of oil mist offsite to adjoining property. Approximately one acre of offsite property was impacted.

Submitted By: David Van der Vieren Received By:

Contact Person: David Van der Vieren

US BANK TOWER 950 17TH ST STE 2200 DENVER, CO 80202

General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: No Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	64	gallons	64	gallons	5	barrels	
Brine	0	barrels	0	barrels			
Other	0	barrels	36	gallons			

Description of Other Released Contaminant:

Snow was recovered in addition

Inspected: Written Report Received: 7/25/2016 Clean Up Concluded: 1/7/2014

Risk Evaluation:

None

Areal Extent:

The release impacted an approximate offsite area of one acre

Potential Environmental Impacts:

The release impacted an approximate offsite area of one acre

Action Taken or Planned:

Placed broken piece of polish rod in stuffing box and closed radigans.

Wastes Disposal Location: Released liquids and contaminated debris were cleaned up to be

disposed of at an approved offsite facility. In the process of delineating offsite area affected; will work with the Bureau of Indian Affairs to

implement appropriate clean up strategy.

Agencies Involved: TAT, BLM, BIA

Updates

Date: 1/21/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release due to polish rod break, sprayed off location, according to the report. Follow-up necessary.

Date: 1/22/2014 Status: Reviewed - Assigned to Other Agency Author: Miller, Adam

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spill occurred within the boundaries of MHA Nation. Spill report forwarded to MHA/BIA authorities.